

3.M.Nº	ELEV.	DESCRIPTION	B.M. Nº	ELEV.	DESCRIPTION	B.M.Nº	ELEV.	DESCRIPTION	B.M.Nº	ELEV.	DESCRIPTION	B.M. Nº	ELEV.	DESCRIPTION
Ì	996.40	West end spillway. (Flowline)	14	1013.78	Spike in 2nd telephone pole west of intersection Co.Rds 98 & 254, south side paym't.	27	1008.81	R.R. Spike in 48" Ash,75 east & S.R.117 in fence row, 2000 north of S.R.273, east of pipeline marker.	40	1014.18	Spike in power pole #200196 at S.E cor. S.R. 235 & Ash Ave.	53	999.35	Nail in power pole *196790, west side S.R. 366, at State & Sta. 979+00.
2	1000.34	"X" in concrete above west end spillway.	15	1005.05	Spike in power pole *192728, 2nd pole south of BreezyDr., west side Co.Rd. 254.	28	1007.99	Spike in telephone pole, east side S.R.117, 120' south of Hardin-Logan County sign.	41	1031.35	Spike in power pole #238889, south side S.R. 235 at Co. Rd. 93.	54	997.19	U.S.G.S. Lakeview, Chiseled square on curb west of catch basin opposite intersection S.R. 366 & 235.
3	1000.15	Punch hole in concrete above east end spillway	16	1006.93	Spike in power pole *87073, north side Co. Rd. 254, N.W. of Ed Galvin mailbox 183 O'Connors Landing.	29	1012.63	U.S.G.S. Chiseled square, west end traffic island in intersection S.R. 117 & 235.	42	1029.52	Spike in telephone pole, north side S.R. 235,1500' west of road T-93, east of State Park.	55	999.60	Spike in power pole *196779, north side S.R. 366, 1st. pole east of Gillette Bait House.
4	1006.99	Spike in power pole #192563, 1st. pole east of Marion Dr., North side of SR.366	17	1003.09	Spike in 24" Sycamore, south side Co. Rd. 254, 1200 west of road T-38.	30	1005.05	Spike in power pole #200462, south side S.R. 235, I600' west S.R. 117.	43	1029.87	Spike in light pole #375506, south side S.R 235 at entrance to camp_area.	56	1000.19	Spike in power pole #192394, north side S.R. 366 at Logan Ave., 1st. pole east McDonalds Gifts sign.
5	1005.25	Punch hole in N.E. corner concrete head- wall, north side S.R. 366, 300' west of road T-95.	18	1007.10	Spike in 24" Cottonwood, north side of Co. Rd. 38, 800'east of O'Connor Road.	31	1002.26	Spike in power pole *200453, south side S.R. 235 at Parker Drive.	44	1020.71	Spike in telephone pole, north side S.R. 235, 400' east of road T-281.	57	999.77	Spike in power pole *192385, north side S.R. 366, 2nd pole east Midway Ave.
6	1010.34	Spike in power pole *192603, north side of intersection S.R. 366 & 368.	19	1012.09	Spike in telephone pole * 9922, north side Co. Rd. 38, 1650' east of road T-38, west of John McDuffee res.	32	1001.92	Spike in power pole *200444, north side S.R. 235, 1700' east of road T-251.	45	1022.90	Spike in guy pole opposite power pole "196955, south side S.R. 235, 1500' east of S.R. 366.	58	998.65	Spike in power pole #192376, north side S.R. 366, west of Russells Point Corp. sign.
7	1012.76	Spike in telephone pole *065EA, north pole on south side of S.R. 366, 1600'± east S.R. 368	20	1026.00	Spike in telephone pole, north side of Co. Rd. 38, 200' east of windmill, 1100' west of S.R. 117.	33	1007.30	Spike in power pole #238023, south side S.R. 235, 250' east of road T-251.	46	1021.39	R.R. Spike in 22"Cedar, S.W.cor. intersection S.R. 235 & 366, in cemetery west of Ritchey Monument.	59	1002.51	Spike in power pole *192365, east side S.R. 366, 300' south of curve.
8	1023.43	Spike in telephone pole south side S.R. 366 at lane west of "O'Connor" lodge sign, 2500'± east S.R. 368	21	1021.62	Top concrete R/W monument, east side SR.117, 70' north Co. Rd. 38.	34	1002.19	Spike in power pole #200423, south side S.R. 235 at Logan Co. bridge 235-2390.	47	1001.23	Spike in telephone pole, west side S.R. 366, north of Sunview Drive.	60	1000.97	Spike in power pole #192190, east side SR. 366, 2nd. pole south of Wilgus Drive.
9	1030.39	Spike in power pole, north Roaches Outboard Motor Repair Shop, Co. Rd. 38 N.W. corner intersection.	22	1013.82	Spike in telephone pole, east side S.R.117, 1050. south of S.R. 273, 40 south Hunts-ville-Bellfontaine sign.	35	1013.23	U.S.G.S. Primary Traverse Sta. 91-1013, intersection S.R. 235 & Co. Rd. 250.	48	998.40	Spike in telephone pole **06IDY07, west side SR. 366, IOO' north of Elm Drive.	61	999.77	Spike in 26" Cottonwood, north side S.R. 366 opposite Antonios Restaurant
10	1008.03	Punch mark top step S.W. wingwall covered bridge Co. Rd. 38.	23	1010.72	Top concrete R/W monument, S.E. cor. Columbia Gas lot, SR.117 & 273.	36	1018.42	Spike in power pole *200346, north side S.R. 235, 700' west of S.R. 702.	49	1000.27	Spike in 10" Cottonwood, east side S.R. 366 opposite State Sta. 1034 + 52.91 P.T.	62	1006.50	R.R.Spike in telephone pole, south side S.R. 366 in front of Russells Point Post Office.
11,	1013.52	Spike in power pole #192671, west side Co. Rd 98, 650 north of old school bldg.	24	1005.92	U.S.G.S. N.W. cor. bridge wingwall North Fork Miami River, S.R. 117, 18-SC-1959- 1006.	37	1024.68	Spike in power pole *200340, north side S.R. 235, 200' east of Sassafras Point Road.	50	1000.09	U.S.G.S. 46-SC-1959-1000 Concrete base of service station sign, west side S.R. 366 at Co. Rd. 87.	63	1000.46	R.R.Spike in power pole *187555, north side S.R. 366 at Russells Point Corp. sign.
12	1014.60	Spike in power pole *192678, west side Co. Rd. 98, 250' south of road T-96.	25	1008.05	Spike in power pole $\frac{$^{2.70}}{5_6}$, west side S.R.117, 1750' north of bridge.	38	1018.43	R.R. Spike in power pole, north side S.R. 235, west of Oak Street.	51	1001.41	Spike in guard rail, west side SR. 366 at State & Sta. 1006 +07.	64	1000.56	Spike in power pole *192532, north side S.R. 366, 850' east of Artist Island.
13	1017.09	Spike in power pole *192701, west side Co. Rd. 98, 1650' north of road T-96.	26	1009.89	Spike in powerpole *39, west side S.R.117 60' south S.R. 273.	39	1022.51	N.W corner concrete pump base at Bornes Store, south side S.R 235.	52	999.70	Spike in power pole #196799, east side SR 366 at State & Sta. 992+30.	65	1000.10	Nail in concrete wall, north side S.R. 366 opposite Stephonson Bait & Tackle Shop drive.

NOTE: All Bench Marks, with the exception of 1, 2, 3, 5, 10, 21, 23, 24, 29, 35, 39, 50, 54, and 65, have the Bench Mark Nº and elevation stamped on an attached metal tag. All Bench Marks are painted

STATE OF OHIO OFFICE OF LAKE LANDS ADMINISTRATOR

> INDIAN LAKE LOGAN COUNTY

BENCH MARKS-PRIMARY CIRCUIT

KOHLI & KALIHER ASSOC.

LIMITED

ENGINEERS & SURVEYORS

LIMA, OHIO 4580I

DRAWN BY: B.W.A

DATE: 4-27-76

SURVEYED BY: T.J.M.

DATE: 4-27-76