



3-16-43 Iron bar found and recognized as corner reestablished from old surveys.  
The above mentioned iron was removed and concrete monument set at this point 3 inches below road surface

Hane Kerns  
Fay Hurst  
R. H. Reed

MONUMENT stamped as directed above  
3/20/43 R.H.R.

