## KIEFFER to MURPHY or BOCKOVEN DESCRIPTION

April, 1970

Being situated in Richland Township, Logan County, Ohio; and being a part of V.M.S. #12277.

Beginning at a iron at the southeast corner of Murphy's 5.565 acretract. Said iron bears S 80 - 07'E 752.3 feet with the east line of said 5.565 acre tract from an iron in the south right of way line of State Route #235.

Thence S 80-07°E 49.84 feet to the Shore line of Indian Lake.

The following ten courses follow the shore line of Indian Lake at Spillway level.

Thence S 530 - 08'W 64.44 feet.

Thence S 770 - 42'W 84.08 feet.

Thence N 790 - 40°W 89.53 feet.

Thence N 750 - 47°W 86.05 feet.

Thence S 710 - 28°W 197.61 feet.

Thence N 360 - 10°W 41.40 feet.

Thence N 180 - 44 W 58.01 feet.

Thence N 350 - 37'E 214.64 feet.

Thence N 20 - 23°E 115.52 feet.

Thence N 70 - 08 W 201.32 feet to an iron.

Thence S 80 - 08°E 335.02 feet.

Thence S 280 - 05°W 222.82 feet.

Thence N 600 - 12°E 188,41 feet to an iron.

Thence S 870 - 51°E 318.05 feet to the place of beginning.

Containing 1.26 acres more or less.

Owen K. Shirk

Surveyor 4271

## KIEFFER to HINDELL DESCRIPTION

### April, 1870

Being situated in Richland Township, Logan County, Ohio; and being a part of V.M.S. #12277.

Beginning at an iron in the southwest corner of Hindell's 10.05 acre tract. Said iron bears S 80 - 07'E 752.3 feet with the west line of said 10.05 acre tract from an iron in the south line of State Route #235.

Thence S 870 - 51°E 26.90 feet.

Thence N 560 - 23°E 179.28 feet to an iron.

Thence S 860 - 52'E 195.66 feet to an iron.

Thence N 540 - 58°E 118.96 feet to an iron.

Thence N 70° - 57°E 107.20 feet to an iron.

Thence S 50 - 38°E 3.81 feet to the shoreline of Indian Lake.

The following seven courses follow the shoreline of Indian Lake at Spillway Level.

Thence S 240 -25°W 130.52 feet.

Thence S 830 - 48 W 150.93 feet.

Thence N 660 - 08°W 101.28 feet.

Thence N 860 - 52°W 38.00 feet.

Thence S 570 - 23°W 63.36 feet.

Thence S 580 - 46°W 176.21 feet.

Thence S 53° - 08°W 31.28 feet.

Thence N 80 - 07°W 49.84 feet to the place of beginning.

Containing 0.54 of an acre more or less.

Owen K. Shirk

Surveyor 4271

# KIEFFER (heep) DESCRIPTION April, 1970

Being situated in Richland Township, Logan County, Ohio; and being a part of V.M.S. \$12277.

Beginning at an iron at the southeast corner of Hindella 10.05 apre tract.

Thence N 70° - 57°E 32.63 feet.

Thence S 20 - 06°E 162.60 feet to an iron.

Thence S 330 - 06°E 22.50 feet to a point in the east line of V.M.S. #12277.

Thence with the east line of V.M.S. #12277 S 470 - 48°W 20.00 feet to the shoreline of Indian Lake.

The following five courses follow the Shoreline of Indian Lake at Spillway level.

Thence N 160 - 11°W 35.38 feet.

Thence N 10 - 31°E 140.85 feet.

Thence N 450 - 24°W 20.10 feet.

Thence S 700 - 57°W 12.00 feet.

Thence S 240 - 25°W 5.11 feet.

Thence N 50 - 38 W 3.81 feet to the place of beginning.

Containing 0.04 of an acre more or less.

Owen K. Shirk

Surveyor 4271

### Hindell (New Description)

April, 1970

Being situated in Richland Township, Logan County, Ohio; and being a part of V.M.S. #12277.

Beginning at the intersection of the east line of V.M.S. #12277 and the centerline of State Route #235.

Thence with the centerline of State Route #235 for the following three courses.

Thence N 830-46°W 347.30 feet.

Thence S 720-34°W 934.75 feet.

Thence S 830-14°W 69.0 feet to an iron at the place of beginning for this description.

The following two courses follow the center of an open ditch.

Thence S 110-21°E 202.3 feet to a point, passing thru a iron at 30.1 feet.

Thence S 50-38'E 459.5 feet to an iron.

The following five courses follow the high water line of Indian Lake

Thence S 700-57\*W 107.2 feet to an iron.

Thence S 540-58°W 119.0 feet to an iron.

Thence N 860-52°W 195.7 feet to an iron.

Thence S 560-23'W 179.3 feet to amstake.

Thence N 870-51°W 26.9 feet to an iron.

Thence N 80-07\*W 782.3 feet to the center of State Route #235, passing thru an iron at 752.3 feet.

The following two courses follow the center of State Route #235.

Thence N 820-06°E 102.4 feet.

Thence N 830-140E 497.2 feet to the place of beginning.

Containing 10.05 acres more or less.

Recieved 6-5.89

#### LESLIE H. GEESLIN

REGISTERED SURVEYOR NO. 5248

P O. BOX 274

RUSHSYLVANIA, OHIO 43347

TELEPHONE: (513) 468-2793
BUSHOP SURVEY

June 5, 1989

The following described real estate situated in the State of Ohio, County of Logan, Township of Richland, being part of Virginia Military Survey 12277 and more particularly described as follows:

Commencing at a 3" iron pipe monument at the southwest corner of R. E. Bockoven's 5.565 acre tract as described in D. B. Vol. 329 Page 771.

Thence N. 50° 48' 40" W. 61.04 feet to a corner of said Bock-oven's 1.26 acre tract as described in D. B. Vol. 331 Page 865 for the place of beginning for this survey.

Thence with the shoreline of Indian Lake N.  $5^{\circ}$  29' 13" W. 79.61 feet to a point.

Thence with said shoreline N. 54° 18' 48" E. 163.26 feet to a point in the west line of said 1.26 acre tract.

Thence with said west line S. 35° 37' W. 214.64 feet to the place of beginning.

Containing 5616 sq. Ft. or 0.129 acre more or less.

Bearings are based on the west line of R. E. Bockoven's 1.26 acre tract (D. B. Vol. 331 Page 865) in this field survey.



INDEXED ON MAP 4695 3D

DESLIE H. GEESLIN XISHISTINANIA, OHIO



