
LOT 267 80.00' 90°05.00" BAYVIEW LANE (20") 268 00 00 LOT 269 80.00. LOT 270 LEGEND: 1 = 5/8 INCH IRON BAR

SCALE: 1": 20'

SET

SURVEY OF LOTS Z68 No. Z69 'N
AVONDALE PACK ALLOT. No. 3,
VIRGINIA MILITARY SURVEY 12276,
STOKES TOWNSHIP, LOGAN COUNTY,
OHIO FOR PHILLIP HULL
ON OCTOBER 29, 1991





SLANDVIEW COURT

LESLIE H. GEESLIN RUSHSLYVANIA, OH (513) 468-2793 * RECID 12-3-09 SUM QU

Lee Surveying and Mapping Co., Inc.

Land Surveys . Topography . Subdivisions . Construction Layout

117 N. Madriver St. Bellefontaine OH 43311



Phone: (937) 593-7335 Fax: (937) 593-7444 surveys@lsminc.us

HORN 0.024 ACRE

Lying in Virginia Military Survey 12276, Stokes Township, Logan County, Ohio.

Being out of the H. Dean Horn and Mary Jean Horn Lot 290 of Avondale Park Allotment #3 (Plat Cabinet A, Slide 241) as deeded and described in Official Record 810, Page 773, Tract I of the Logan County Records of Deeds and being more particularly described as follows:

Beginning on a 5/8 inch iron rod set on the northeast corner of Lot 289 of Avondale Park Allotment #3 on the west right-of-way of Bayview Lane.

THENCE, with the north line of Lot 289, S 75°-39'-06"W, a distance of 79.98 feet to a 5/8 inch iron rod set on the northwest corner of Lot 289 on the east right-of-way of Lakeview Court (variable widths).

THENCE, with the east right-of-way of Lakeview Court, N 14°-15'-02"W, a distance of 13.00 feet to a 5/8 inch iron rod set.

THENCE, N 75° -39'-06"E, a distance of 79.98 feet to a 5/8 inch iron rod set on the west right-of-way of Bayview Lane.

THENCE, with the west right-of-way of Bayview Lane (20 feet wide), S 14°-15'-23"E, a distance of 13.00 feet to the point of beginning.

Containing 0.024 acre.

The basis for bearings is the west right-of-way of Bayview Lane, being S 14°-15'-23"E, and all other bearings are from angles and distances measured in a field survey by Lee Surveying and Mapping Co., Inc. on November 19, 2009, Revised December 2, 2009.

BRUCE A SONAL SUNITION OF THE PROPERTY OF THE

Description prepared by:

William K. Bruce Professional Surveyor 7437

December 3, 2009

INDEXED ON MAP 8584 ZD

4876119