

BYLER TO KING DESCRIPTION  
(March, 1968)

Being situated in Section 34, Town 5, Range 13, in Liberty Township, Logan County, Ohio-

Beginning at an iron in the center of State Route #508 at the intersection with County Road #192. 177

Thence with the center of State Route #508  $S48^{\circ}-55'E$  34.4 feet to an iron at an angle in the road.

Thence continuing with State Route #508  $S80^{\circ}-19'E$  586.0 feet to an iron at the place of beginning for this description.

Thence continuing with the center of State Route #508  $S80^{\circ}-19'E$  315.2 feet to an iron.

Thence  $S 1^{\circ}-22'W$  351.8 feet to a hub, passing through a corner post at 52.0 feet.

Thence  $N83^{\circ}-56'W$  343.3 feet to an iron.

Thence  $N 6^{\circ}-04'E$  370.5 feet to the place of beginning, passing through an iron at 340.5 feet.

Containing 2.72 acres more or less, being surveyed from a 66.28 acre tract.

---

Owen K. Shirk  
Surveyor 4271

4200 1D

INDEXED ON MAP