

Piatt Survey - Monroe Twp.

Sec. 21 - T5 R-13 Between M.R.S.

Note - Ground was frozen very hard making it impossible to find irons in road. See Book "D" Page 90 for Survey of this west line also see Worthington Survey in field book 380 for E of Mill road East of this survey

INDEXED ON MAP

578

see Drawer R

March-4-1926

Cold Wind
Grand Frozen

Wright

Shanklin

Mr. Piatt

