



ELIZABETH ST. N 38° E (PLANT)

1.02' Excess in Block  
= 0.25' per each 75' Lot

20' ALLEY  
S 37° 59' 20" W  
75.25'

LOT No. 187  
CATHERINE H. GRIFFEN  
VOL. O.R. 30, Pg. 08

GARAGE UNDER CONSTRUCTION  
(NO ENCROACHMENTS)

151.01'  
N 52°-14'-10" W

3.04' EXCESS IN BLOCK  
= 1.01' per each 150'

TRUE MAPLE STREET

CO. ENGR & (SEE FB. 708, PG. 61)

● = 1/2" IRON ROD (SET)

SCALE ~ 1" = 30'

SURVEY OF LOT No. 187  
VILLAGE OF BELLE CENTER  
RICHLAND TWP.  
LOGAN COUNTY, OHIO

I hereby certify that the foregoing plat was prepared from an actual survey of the premises and that same shows the location of the boundaries and all improvements thereon; that the dimensions of the improvements and the locations thereof with respect to the boundaries are correct as shown; that there are no encroachments from nor upon subject premises.



*Clayton M. Lee*

Clayton M. Lee  
Registered Professional Surveyor No. 6181  
April 7, 1987

ORIGINAL STAMP IN GREEN

INDEXED ON MAP  
7676 1P