

Survey for Presbyterian Church
Lot 112 - 111

Bellefontaine

	0.58	100.58		
1-a				
NW Corner			6.81	93.77
1-a			5.8	94.8
1-B			5.8	94.8
1-C			6.0	94.6
1-d			6.0	94.6
1-E			6.5	94.1
SW			7.4	93.2
2-a			6.0	94.6
2-b			6.1	94.5
2-C			6.2	94.4
2-d			5.9	94.7
2-E			6.8	93.8
3-a			5.4	94.2
b			5.9	94.7
c			6.1	94.5
d			6.2	94.4
e			7.1	93.5
4-a			5.1	95.5
b			5.7	94.0
c			5.8	94.8
d			5.6	95.0
e			6.1	94.5
5-a			4.5	96.1
b			5.2	95.4
c			5.2	95.4
d			4.8	95.8
e			5.8	94.7

711


INDEXED ON MAP

Map
Drawer
R.

Weather fair

W.A. Montgomery
D.E. Smucker

47



Survey for Presbyterian Church

Lot 112 - 111

Allegheny

Weather fair

W H Montgomery
D E Smucker

47

FB 417


Lot
NW Corner

0.58 100.58

6.81	93.77
5.8	94.8
5.8	94.8
6.0	94.6
6.0	94.6
6.5	94.1
7.4	93.2
6.0	94.6
6.1	94.5
6.2	94.4
5.9	94.7
6.8	93.8
5.4	94.2
5.9	94.7
6.1	94.5
6.2	94.4
7.1	93.5
5.1	95.5
5.7	94.9
5.8	94.8
5.6	95.0
6.1	94.5
4.5	96.1
5.2	95.4
5.2	95.4
4.8	95.9
	96.7


711 2P-1
INDEXED ON MAP

Map
Drawer
R₁



Top Runway	100 SB		
a		3.4	97.2
b		4.5	96.1
c		4.7	95.9
d		4.8	95.8
e		6.3	93.3
Runway Walk		8.39	92.20
" South		8.56	92.02
Furnace Room		10.50	90.08
Basement Fl.		7.76	92.72
T.P.		2.65	97.93
SE Cor top str basketry teleph Co.	0.58	0.58	100.00
	5.0	102.93	
Side Walk E		5.27	96.34
East Ent.		1.98	100.95

Telephone Bldg



INDEXED ON MAP
711 2P-2