

Brooks Survey  
see BOOK C Page 213

Ran from center of Harlan Mill  
road down pike 9.12 1/2 (360)

$$\begin{array}{r} \text{fence is at } \frac{9.12\frac{1}{2}}{8.73} \\ \hline .39\frac{1}{2} \end{array}$$

Ran from center of Harlan Mill  
road to Pike  
N 76° W 9.92 1/2 + 1  
center of RR. old track

Thence with RR from  
Harlan Mill road at  
8.33 fence set stake  
at 87° 0' = 33.80

$$\begin{array}{r} 8.33 \\ \hline .14 \end{array}$$

May 15, 1889

South line of Shefer place by  
Deed S 76° E

13.64 1/2 to center of pike  
nit stake in pike set  
to Shefer 10 a

N. O. 28° south of <sup>big</sup> gate 86' 6"

S 57° 1/2 W 80' 0"

Line A on Pike from  
above S 73° E  
36.85 to intersection of  
Pike set iron bolt.

Line of Board fence north side  
of cemetery at  $\frac{35.88}{7.91}$  set iron  
pike  $\frac{25.93}{}$

with Francis north side of cam  
S 83 1/2° W 7.85 to stone

With Board Fence west  
side of Cmn -

S 81 1/2 E 7.69 to center of  
Pike (7 x 4)  
from spike -

from + road to center of pike at  
west side of graveyard  
S 82 1/4 W 7.79

From west side graveyard to  
center of Pike at RR  
S 83 W 19.38 1/2  
7.79  
11.59 1/2

With RR  
cut 50' from track  
angle every 5 ch

- 0 - 5 - N 9 1/2 W
- 5 - 10 - N 6 1/2 W
- 10 - 15 - N 4 1/4 W
- 15 - 20 - N 1 W
- 20 - 25 - N 2 1/2 E
- 25 - 30 - N 6 1/4 E
- 30 - 35 - N 9 + E
- 35 - 41.75 - N 12 1/2 E

mit stake NW on RR.  
80.25' <sup>5</sup> N 66 1/2 W 53' dist.

434

INDEXED ON MAP

Samuel Siffis	rd-
R. F. Conshman	ch
Frank Ditty	ch

(434)  
INDEXED ON MAP