



Surveyed for Partition Commissioners,
Martin Miller, Henry McKinnon and
Daniel W. Koch.

S. E. Qr. Sec. 31, ^{1/2} S. E. Qr. Sec. 32, T. 3, R. 14,
Pleasant Tp. ^{1/2} West $\frac{1}{2}$ of N. W. Qr. Sec. 30,
T. 4, R. 13, Union Tp. Surveyed 14, 15 ^{1/2} 19, June 1907.

~Description of Corners~

- A-Stone, with five empty bottles.
- B-Stone 4ft. north of center of gravel on Degraff pike.
- C-Stone-Wit: Fence post 9 lks. north $\frac{2}{3}$ 12" Apple tree 18" S.E.
- D-Stone-Wit: 4" Peach tree 2ft. east $\frac{3}{2}$ 5" Apple tree 22 lks. S.E.
- E-Stone- 8" square on top, with pieces of drain tile.

O. C. Richey }
W. H. Tamplin } Chain Cr.
H. J. Tamplin }

Herbert Tamplin }
Harry Castle } Flagman



Scale: 1 in. = 10 chains

Charles M. Richey
County Surveyor