## RICHARD CUMMINS DESCRIPTION (June, 1967)

Being situated in Rushereck Township, Logan County, Ohio; and being a part of V.M.S. 9952 and V.M.S. 9953 -

Reginning at an iron where the center line of County Road lol intersects the north-south line between V.M.S. 9952 and V.M.S. 9953.

Thence with the line between V.H.S. 9952 and 9952 S 80-03'E 381.5 feet to a corner post.

Thence N820-21'E 417.0 feet to an iron.

Thence S 50-00'W 638.5 feet to an S" ash tree.

Thence S42°-25'E 208.5 feet to the west side of a double hickory tree.

Thence S130-55'E 195.0 feet to en iron.

Thence S81°-57'W 417.0 feet to a corner post in the line between V.M.S. 9952 and V.M.S. 9953.

Thence B350-49'W 762.3 feet to a hub.

Thence N370-49'W 280.2 feet to an iron in the center of County Road #101.

Thence with the center of County Road 101 N460-36'E 613.0 feet to the place of beginning.

Containing 15.32 seres more or less.

from a 40.0 acre tract in V.M.S. 9952, and the remainder

75.33

Owen K. Shirk Surveyor 4271

INDEXED ON MAP

