



- SYMBOLS:
- - R. R. Spikes Fd.
  - ⊗ - 5/8" x 30" Rebars Fd.
  - ⊠ - 5/8" x 30" Rebars Set.



<b>MARSHALL SURVEY</b>		
Section No. 17, Town 4, Range 13 BMRS.		
Union Township, Logan County, Ohio.		
SCALE: 1" = 200'	APPROVED BY:	DRAWN BY: DEG
DATE: 12-28-1998		REVISED:
Daniel E. Gilbert, P.S. Reg. Sur. No. 5402		DRAWING NUMBER 098-042

INDEXED ON MAP  
5694

S-540